

AC Cooling Performance & Heater Operations

Cigarette Lighter

The Work Book, Ground Floor, HiLITE Business Park Kozhikode - 673014, Kerala, India.

E-mail: sureshdrives@gmail.com | W: www.sureshdrives.com

Mob. & WhatsApp: +91 8138 00 29 84

MSME Reg: UDYAM-KL-08-0025214 | GSTIN: 32BFPPS5156C1ZD

Ins	pection

Date of Inspection:	Customer Name:			
17-02-2025	Mr.XXXX			
Vehicle:	Registration number:			
BENZ E250	KL 11 AU ****			
Date of Registration:	Model Year:			
05-04-2014	2013			
Chassis Number:	Engine Number:			
WDD2120046L03****	6519243189****			
Kilometers at Inspection: 70803				
E- Exellent Condition	■ G- Good Condition		B- Bad	l Conditio
INTERIOR CONDITION		E	G	В
Door Panels		0	•	0
Dash Pad		0	•	0
Glove Box		0		0

INTERIOR CONDITION	E	G	В
Vanity Mirrors & Sun visors	0		0
Hand brake lever / buttons	0		0
Control buttons & levers	0		0
Hood Release	0		0

GAUGES,AUDIO SYSTEM & NAVIGATION	E	G	В
Speedometer	0		0
Tachometer	0		0
Temperature	0		0
Oil Pressure	0		0
Warning Messages & Symbols	0		0
Audio System & Speakers	0		0
Navigation System	0	0	0
Keyless Entry / Ignition system	0		0

CARPET, UPHOLSTERY & TRUNK	E	G	В
Front Seats	0		0
Front Carpeting	0		0
Headliner & Head rests	0	•	0
Rear Seats	0	•	0
Rear Carpeting	0	•	0
Trunk Carpeting	0	•	0
Tools	0	•	0
Jack	0	•	0
Spare Tire	0		0
Floor Pan	0		0

ELECTRICAL SYSTEM	\mathbf{E}	G	В
Head Lights	0		0
Tail Lights	0	•	0
Brake Lights	0		0
Parking Lights	0		0

ELECTRICAL SYSTEM	E	G	В
Turn Signals	0	•	0
Electric Seats	0	•	0
Sunroof Motors	0	•	0
Power Window	0		0
Blinds	0	0	0
ORVM Electrical Mirrors	0	•	0

UNDER THE HOOD	E	G	В
Fluids Condition	0	0	0
Oil Leaks	0	0	0
Coolant Leaks	0	0	0
Drive Belts/Timing Belts	0	•	0
Engine Mountings	0	•	0
Steering Components	0	•	0
Turbo	0	•	0
All Rubber Boots/Gaiters	0	•	0
Rat Bits	0	0	0
Looped Wires	0	0	0
Exhaust Leaks	0	•	0
Exhaust Smoke	0	•	0
Evidence of Smoke	0	•	0
Abnormal Noise	0	•	0

UNDER THE CAR		E	G	В
Drive Line		0	•	0
Differential		0	•	0
Under Body	(0	•	0
Exhaust	(0	•	0

ROAD TEST	E	G	В
Idle	0	•	0
Engine Starting	0	•	0

ROAD TEST	E	G	В
Acceleration	0		0
Tyre Condition	0		0
Engine Noise	0		0
Steering Effort - Cornering Right or Left	0		0
Engine Operating Temperature	0	•	0
Transmission Shift Quality, Smoothness, Effort, Slippage	0	•	0
Transmission/Transaxle Noise	0		0
CV Joint/Drive Axle Noise	0		0
Parking Brake Operation	0	•	0
Engine Performance	0		0
Cooling System Efficiency	0		0

FINAL INSPECTION SUMMARY	${f E}$	G	В
Body Condition	0	•	0
Engine Condition	0		0
Cooling Condition	0		0
Interior Items	0		0
Gauges	0	•	0
Audio System	0	•	0
Carpet & Upholstery	0	•	0
Under the Hood	0	•	0
Under the Car	0	•	0
Electrical System	0	•	0
Battery Condition	0	•	0
Glass	0	•	0
Trunk	0		0
Tires & Wheels	0		0
Car Scanning Report	0	•	0
Road Test	0	•	0

BREAK	
Noise	

BREAK	
Vibration	
Effort	
SUSPENSION	
OK	
Noise	
Rough	
Week	
COMMENTS	

***NOTE:PLEASE CROSS-CHECK THIS INSPECTION REPORT WITH THE VEHICLE'S

*Front suspension week -front left shock leak

SERVICE HISTORY BEFORE PURCHASING ***

*AC Compressor pipe leak

*Front both link rod need to be replace

View Images

Name of Technician: Gokul



