

The Work Book, Ground Floor, HiLITE Business Park Kozhikode - 673014, Kerala, India.

E-mail: sureshdrives@gmail.com | W: www.sureshdrives.com

Mob. & WhatsApp: +91 8138 00 29 84

MSME Reg: UDYAM-KL-08-0025214 | GSTIN: 32BFPPS5156C1ZD

T	
Ins	pection

Date of Inspection:	Customer Name:			
29-05-2025	Mr.XXXX			
Vehicle:				
HYUNDAI VERNA 1.5 TURBO GDI	Registration number:			
DCT SX	KL 03 AH XXXX			
Date of Registration:	Model Year:			
29-07-2024	2023			
Chassis Number:	Engine Number:			
MALGU41CVPM0XXXXX	G4LHPM5XXXXX			
Kilometers at Inspection: 12216				
- Exellent Condition	Good Condition	<b>E</b> E	3- Bad	Condition
NTERIOR CONDITION		B	G	В
Door Panels			<b>O</b>	<b>D</b>
Dash Pad		0	0	0
Glove Box		0	•	0
AC Cooling Performance & Heater Operations				

INTERIOR CONDITION	E	G	В
Cigarette Lighter	0	0	0
Vanity Mirrors & Sun visors	0		0
Hand brake lever / buttons	0		0
Control buttons & levers	0		0
Hood Release	0		0

GAUGES,AUDIO SYSTEM & NAVIGATION	E	G	В
Speedometer	0		0
Tachometer	0		0
Temperature	0		0
Oil Pressure	0		0
Warning Messages & Symbols	0		0
Audio System & Speakers	0		0
Navigation System	0		0
Keyless Entry / Ignition system	0		0

CARPET, UPHOLSTERY & TRUNK	$\mathbf{E}$	G	В
Front Seats	0		0
Front Carpeting	0		0
Headliner & Head rests	0		0
Rear Seats	0		0
Rear Carpeting	0		0
Trunk Carpeting	0		0
Tools	0	•	0
Jack	0		0
Spare Tire	0	•	0
Floor Pan	0		0

ELECTRICAL SYSTEM	E	G	В
Head Lights	0		0
Tail Lights	0		0
Brake Lights	0		0

ELECTRICAL SYSTEM	E	G	В
Parking Lights	0		0
Turn Signals	0	•	0
Electric Seats	0	•	0
Sunroof Motors	0	•	0
Power Window	0		0
Blinds	0		0
ORVM Electrical Mirrors	0		0

UNDER THE HOOD	E	G	В
Fluids Condition	0		0
Oil Leaks	0	0	0
Coolant Leaks	0	0	0
Drive Belts/Timing Belts	0	•	0
Engine Mountings	0	•	0
Steering Components	0	•	0
Turbo	0	•	0
All Rubber Boots/Gaiters	0	•	0
Rat Bits	0	0	0
Looped Wires	0	0	0
Exhaust Leaks	0	0	0
Exhaust Smoke	0	•	0
Evidence of Smoke	0	0	0
Abnormal Noise	0	0	0

UNDER THE CAR	E	G	В
Drive Line	0	•	0
Differential	0	0	0
Under Body	0	•	0
Exhaust	0	•	0

ROAD TEST	E	G	В
Idle	0		0

ROAD TEST	E	G	В
Engine Starting	0	<b>O</b>	0
Acceleration	0		0
Tyre Condition	0		0
Engine Noise	0		0
Steering Effort - Cornering Right or Left	0		0
Engine Operating Temperature	0		0
Transmission Shift Quality, Smoothness, Effort, Slippage	0		0
Transmission/Transaxle Noise	0	<b>O</b>	0
CV Joint/Drive Axle Noise	0		0
Parking Brake Operation	0		0
Engine Performance	0	•	0
Cooling System Efficiency	0		0

FINAL INSPECTION SUMMARY	D	G	В
Body Condition	0		0
Engine Condition	0		0
Cooling Condition	0		0
Interior Items	0		0
Gauges	0		0
Audio System	0	•	0
Carpet & Upholstery	0	•	0
Under the Hood	0	•	0
Under the Car	0		0
Electrical System	0		0
Battery Condition	0	•	0
Glass	0	•	0
Trunk	0	•	0
Tires & Wheels	0	•	0
Car Scanning Report	0	•	0
Road Test	0	•	0

Noise	
Vibration	
Effort	

SUSPENSION	
OK	
Noise	
Rough	
Week	

## **COMMENTS**

NOTE: \*Please cross-check this inspection report with the vehicle's service history and insurance claim records before purchasing. This report reflects the vehicle's condition at the time of inspection and does not guarantee future performance.\*

\* There is an oil leak from the engine valve cover and CAM seals -minor

View Images

Name of Technician: Ebin



