

The Work Book, Ground Floor, HiLITE Business Park Kozhikode - 673014, Kerala, India. E-mail: sureshdrives@gmaiLcom | W: www.sureshdrives.com Mob. & WhatsApp: +91 8138 00 29 84 MSME Reg: UDYAM-KL-08-0025214 | GSTIN: 32BFPPS5156C1ZD

Inspection

Date of Inspection:	Customer Name:	
13-05-2025	Mr.XXXX	
Vehicle:	Registration number:	

BMW X1 sDrive 20d Expedition	KL 07 CQ 0775

Date of Registration:	Model Year:
29-10-2018	2018

Chassis Number:

Engine Number:

WBAHU1701J5JXXXXX	015XXXXX
-------------------	----------

Kilometers at Inspection:

69745

E- Exellent Condition

📒 G- Good Condition

B- Bad Condition

INTERIOR CONDITION	E	G	B
Door Panels	0	\bigcirc	\bigcirc
Dash Pad	0		0
Glove Box	0		0
AC Cooling Performance & Heater Operations	0		0
Cigarette Lighter	0	0	0

INTERIOR CONDITION	E	G	B
Vanity Mirrors & Sun visors	0	\bigcirc	0
Hand brake lever / buttons	0	\bigcirc	0
Control buttons & levers	0	\bigcirc	0
Hood Release	0		0

GAUGES,AUDIO SYSTEM & NAVIGATION	E	G	B
Speedometer	0	\bigcirc	0
Tachometer	0	\bigcirc	0
Temperature	0	\bigcirc	0
Oil Pressure	0	\bigcirc	0
Warning Messages & Symbols	0	\bigcirc	0
Audio System & Speakers	0	\bigcirc	0
Navigation System	0	0	0
Keyless Entry / Ignition system	0	\bigcirc	0

CARPET, UPHOLSTERY & TRUNK	E	G	B
Front Seats	0		0
Front Carpeting	0	\bigcirc	0
Headliner & Head rests	0	\bigcirc	0
Rear Seats	0	\bigcirc	0
Rear Carpeting	0	\bigcirc	0
Trunk Carpeting	0	\bigcirc	0
Tools	0	\bigcirc	0
Jack	0	\bigcirc	0
Spare Tire	0	\bigcirc	0
Floor Pan	0	\bigcirc	0

ELECTRICAL SYSTEM	E	G	B
Head Lights	0	0	0
Tail Lights	0		0
Brake Lights	0	۲	0
Parking Lights	0	۲	0

ELECTRICAL SYSTEM	E	G	В
Turn Signals	0	\bigcirc	0
Electric Seats	0	\odot	0
Sunroof Motors	0	0	0
Power Window	0	\odot	0
Blinds	0	0	0
ORVM Electrical Mirrors	0	۲	0

UNDER THE HOOD	E	G	B
Fluids Condition	0	۲	\bigcirc
Oil Leaks	0	0	0
Coolant Leaks	0	0	0
Drive Belts/Timing Belts	0	۲	0
Engine Mountings	0	0	۲
Steering Components	0	۲	0
Turbo	0	۲	0
All Rubber Boots/Gaiters	0	0	۲
Rat Bits	0	0	0
Looped Wires	0	0	0
Exhaust Leaks	0	0	0
Exhaust Smoke	0	۲	0
Evidence of Smoke	0	0	0
Abnormal Noise	0	0	0

UNDER THE CAR	E	G	B
Drive Line	0	۲	0
Differential	0	0	0
Under Body	0	۲	0
Exhaust	0	۲	0

ROAD TEST	E	G	B
Idle	0	\bigcirc	0
Engine Starting	0	\bigcirc	0

ROAD TEST	E	G	B
Acceleration	0	\bigcirc	0
Tyre Condition	0	0	\bigcirc
Engine Noise	0	\bigcirc	0
Steering Effort - Cornering Right or Left	0	\bigcirc	0
Engine Operating Temperature	0	\bigcirc	0
Transmission Shift Quality, Smoothness, Effort, Slippage	0		0
Transmission/Transaxle Noise	0		0
CV Joint/Drive Axle Noise	0		0
Parking Brake Operation	0		0
Engine Performance	0		0
Cooling System Efficiency	0	\bigcirc	0

FINAL INSPECTION SUMMARY	E	G	B
Body Condition	0	0	0
Engine Condition	0		0
Cooling Condition	0		0
Interior Items	0		0
Gauges	0		0
Audio System	0		0
Carpet & Upholstery	0	\bigcirc	\bigcirc
Under the Hood	0	\bigcirc	\bigcirc
Under the Car	0		0
Electrical System	0		0
Battery Condition	0		0
Glass	0		0
Trunk	0		0
Tires & Wheels	0	0	
Car Scanning Report	0		0
Road Test	0		0

BREAK	
Noise	

BREAK	
Vibration	
Effort	

SUSPENSION		
ОК		
Noise	I	
Rough		
Week		

COMMENTS

NOTE: *Please cross-check this inspection report with the vehicle's service history and insurance claim records before purchasing. This report reflects the vehicle's condition at the time of inspection and does not guarantee future performance.*

- * The engine mounting is broken, and there is vibration when starting.
- * The front tires are not wearing properly, only the inside is wearing out- need to do wheel alignment
- * The front and rear shock absorbers are weak, and the boots on the link rods are broken.
- * See a dot on the infotainment system screen.

View Images

Name of Technician:Ebin



