

AC Cooling Performance & Heater Operations

Cigarette Lighter

The Work Book, Ground Floor, HiLITE Business Park Kozhikode - 673014, Kerala, India.

E-mail: sureshdrives@gmail.com | W: www.sureshdrives.com

Mob. & WhatsApp: +91 8138 00 29 84

MSME Reg: UDYAM-KL-08-0025214 | GSTIN: 32BFPPS5156C1ZD

Ins	pection

Date of Inspection:	Customer Name:	
03-05-2025	Mr.XXXX	
Vehicle:	Registration number:	
MAHINDRA XUV 300 W8	KL 78 C XXXX	
Date of Registration:	Model Year:	
11-08-2023	2023	
Chassis Number:	Engine Number:	
MA1NM2EW4P2DXXXXX	EWPZDXXXXX	
Kilometers at Inspection: 24257		
- Exellent Condition	G- Good Condition	■ B- Bad Conditio
INTERIOR CONDITION		E G B
Door Panels		0 0
Dash Pad		0 0
Glove Box		

INTERIOR CONDITION	E	G	В
Vanity Mirrors & Sun visors	0		0
Hand brake lever / buttons	0		0
Control buttons & levers	0		0
Hood Release	0		0

GAUGES,AUDIO SYSTEM & NAVIGATION	E	G	В
Speedometer	0		0
Tachometer	0		0
Temperature	0		0
Oil Pressure	0		0
Warning Messages & Symbols	0		0
Audio System & Speakers	0		0
Navigation System	0	0	0
Keyless Entry / Ignition system	0		0

CARPET, UPHOLSTERY & TRUNK	E	G	В
Front Seats	0		0
Front Carpeting	0		0
Headliner & Head rests	0	•	0
Rear Seats	0	•	0
Rear Carpeting	0	•	0
Trunk Carpeting	0		0
Tools	0		0
Jack	0	•	0
Spare Tire	0		0
Floor Pan	0		0

ELECTRICAL SYSTEM	\mathbf{E}	G	В
Head Lights	0		0
Tail Lights	0	•	0
Brake Lights	0		0
Parking Lights	0		0

ELECTRICAL SYSTEM	E	G	В
Turn Signals	0		0
Electric Seats	0	0	0
Sunroof Motors	0	•	0
Power Window	0	•	0
Blinds	0	•	0
ORVM Electrical Mirrors	0	•	0

UNDER THE HOOD	E	G	В
Fluids Condition	0		0
Oil Leaks	0	0	0
Coolant Leaks	0	0	0
Drive Belts/Timing Belts	0	•	0
Engine Mountings	0	•	0
Steering Components	0	•	0
Turbo	0	0	•
All Rubber Boots/Gaiters	0	0	
Rat Bits	0	0	0
Looped Wires	0	0	0
Exhaust Leaks	0	0	0
Exhaust Smoke	0	•	0
Evidence of Smoke	0	0	0
Abnormal Noise	0	0	0

UNDER THE CAR	E	G	В
Drive Line	0	•	0
Differential	0	0	0
Under Body	0	•	0
Exhaust	0	•	0

ROAD TEST	E	G	В
Idle	0	•	0
Engine Starting	0	•	0

ROAD TEST	E	G	В
Acceleration	0		0
Tyre Condition	0		0
Engine Noise	0		0
Steering Effort - Cornering Right or Left	0		0
Engine Operating Temperature	0		0
Transmission Shift Quality, Smoothness, Effort, Slippage	0		0
Transmission/Transaxle Noise	0		0
CV Joint/Drive Axle Noise	0		0
Parking Brake Operation	0		0
Engine Performance	0		0
Cooling System Efficiency	0		0

FINAL INSPECTION SUMMARY	E	G	В
Body Condition	0	0	0
Engine Condition	0		0
Cooling Condition	0		0
Interior Items	0		0
Gauges	0		0
Audio System	0		0
Carpet & Upholstery	0		0
Under the Hood	0	•	0
Under the Car	0	•	0
Electrical System	0		0
Battery Condition	0		0
Glass	0	•	0
Trunk	0	•	0
Tires & Wheels	0	•	0
Car Scanning Report	0	•	0
Road Test	0		0

BREAK	
Noise	

BREAK	
Vibration	
Effort	
SUSPENSION	
OK	
Noise	
Rough	
Week	

COMMENTS

NOTE: *Please cross-check this inspection report with the vehicle's service history and insurance claim records before purchasing. This report reflects the vehicle's condition at the time of inspection and does not guarantee future performance.**

* The following parts have changed as part of an accident;

Front bumper, grill, headlight, fender etc....

View Images

Name of Technician:Ebin



